

QUOTATION Q.17716



Issue Date: 3 August 2023

Department of Biochemistry
Faculty of Dentistry
Chulalongkorn University
Henri-Dunant Road
Patumwan
Bangkok 10330
THAILAND

TgK Scientific Limited
7 Longs Yard
Bradford-on-Avon
Wiltshire
BA15 1DH
United Kingdom

Telephone: +44 (0)1225 868699
E-mail: hi-tech@tgkscientific.com
Web Site: <http://www.hi-techsci.com>

Item No.	Ref. No.	Description	Qty	Total
1	NB4518	PTFE Drive Valve including screws and key NA 5084 For SF-61SX2/SF-61DX2	4	1,280.00

Total FOB UK Shipping Point	£1,280.00
Cost, Insurance and Freight (CIF)	150.00
Total CIF	£1,430.00
	(GBP)

VALIDITY:	This quotation is valid until 2 September 2023
DISPATCH:	Within 2 weeks of receipt of a purchase order.
TERMS:	Nett, 30 days from date of invoice, by Bank Transfer in Pounds Sterling. <i>Contact TgK Scientific for bank details.</i> NOTE: Payment <u>must</u> be free from all taxes/charges to the beneficiary.
IMPORT:	To be paid by the Customer, if applicable. N.B. The equipment described in this quotation is classified under Combined Nomenclature 9027.30.00. This allows the equipment to be imported 'Duty Free'.
CONDITIONS:	This quotation is provided within our standard Terms and Conditions of Trade, available on request.
WARRANTY:	1 year standard warranty.
SIGNATURE:	For and on behalf of TgK Scientific Limited

Ganesh Pathmanayagam, Sales Engineer
ganeshp@tgkscientific.com

TgK Scientific Limited, Registered Office:
30 Gay Street, Bath, BA21 2PA, United Kingdom
Company Registered in England & Wales Number 5364812





บันทึกข้อความ

ส่วนงาน ภาควิชาชีวเคมี คณะทันตแพทยศาสตร์ โทร. ๐๒-๒๑๘๘๖๗๐-๗๙

ที่ ขว๒๕/๒๕๖๖

วันที่ ๔ สิงหาคม พ.ศ. ๒๕๖๖

เรื่อง ขออนุมัติซ่อมเครื่อง stopped-flow spectrometer

เรียน รองคณบดีฝ่ายวิจัย

สิ่งที่ส่งมาด้วย ๑. ใบเสนอราคา

๒. ใบส่งซ่อม

๓. ประวัติการซ่อม

ด้วย เนื่องจากเครื่อง stopped-flow spectrometer เลขที่ครุภัณฑ์ ๓๓๒๒๘๐๐๐๒๘๙๓ วจ./๕๙ (๓.๗) ได้ใช้มาเป็นเวลา ๕ ปี จึงทำให้วาล์วที่ใช้ในการผสมสารเสื่อมสภาพและพบว่าการรั่วซึม จึงไม่สามารถใช้ในงานที่ต้องทำภายใต้ภาวะไร้ออกซิเจน (anaerobic condition) เนื่องจากมีการรั่วซึมของออกซิเจนเข้ามาในระบบ และในงานวิจัยจำเป็นต้องใช้ภาวะดังกล่าว เพื่อให้งานวิจัยสามารถดำเนินต่อไปได้ จึงจำเป็นต้องซ่อมวาล์วดังกล่าวโดยการเปลี่ยนหัววาล์วโพลีเมอร์ polytetrafluoroethylene (PTFE) ที่ควบคุมการไหลจำนวน ๔ ตำแหน่ง เป็นจำนวนเงิน ๑,๔๓๐ ปอนด์สเตอร์ลิงสหราชอาณาจักร (ตามใบเสนอราคา) หรือประมาณ ๖๓,๑๗๕.๙๕ บาท ทั้งนี้ตามอัตราแลกเปลี่ยน

จึงเรียนมาเพื่อโปรดพิจารณาอนุมัติให้ด้วย จักเป็นพระคุณยิ่ง

เรียนคุณชำนาญ
เพื่อโปรดดำเนินการ

(รองศาสตราจารย์ทันตแพทย์ ดร.จิรัสย์ สุจริตกุล)

วันที่ 04 ส.ค. 2566 เวลา 12:42

หัวหน้าภาควิชาชีวเคมี